## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



						0144
Intersection ID: N/A	Main Street: PINEVILLE-MATTHEWS_RD	Cross Street:	CHALLIS_FARM_RD		Location:	SW
ADA ID: 670544AA2280	Ramp Type: PerpDiag	Initial Pass/Fa	ail: Fail Overall (	Compliance	e: No Severity Score:	21.25
Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance						
	Possible Solutions:	Comp	Compliance Description		Data Compliance Description	
	Remove & Replace Curb Ramp Wit	th N/A	Ramp Length (in)	61.0 N	No Ramp Slope (%)	8.5
	Two New Directional Ramps or	No	Ramp Width (in)	40.0 Y	Yes Ramp XSlope (%)	0.3
	Equivalent.	N/A	Flare Type LT	N/A	N/A Flare Type RT	N/A
		N/A	Flare Slope LT (%)	N/A	N/A Flare Slope RT (%)	N/A
		N/A	Flare Traversable LT?	N/A	N/A Flare Traversable RT?	N/A
WITH BE		N/A	Landing Length (in)	N/A	N/A DWS Provided?	N/A
TUBALL	Surveyor Notes:	N/A	Landing Width (in)	N/A	N/A DWS Contrast?	N/A
and and a second a se	N/A	N/A	Landing Slope (%)	N/A	N/A DWS Length (in)	N/A
5.6/10 4 8	A Sector Man	N/A	Landing X Slope (%)	N/A	N/A DWS Full Width?	N/A
100 300	A State	N/A	Landing Curb? (Y/N)	N/A	N/A DWS Offset (in)	N/A
	a state of the sta	N/A	Shared Landing?	N/A		
San	PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A Gutter Slope (%)	N/A
	Not Found, R304.5.1, R304.2.2	N/A	Gutter Lip Ht (in)	N/A	N/A Gutter X Slope (%)	N/A
the state of the second second second		N/A	Painted X Walk1?	No N	N/A Painted X Walk2?	No
	1.000		X Walk 1 Direction	To NE	X Walk 2 Direction	To N
		N/A	X Walk 1 Width (in)	N/A	N/A X Walk 2 Width (in)	N/A
Street 1 Name EN1	TRANCE		X Walk 1 Slope (%)	3.9	X Walk 2 Slope (%)	0.6
Stop Condition-Street 2 S	StopSign		X Walk 1 X Slope (%)	0.6	X Walk 2 X Slope (%)	2.5
Street 2 Name PINEVILLE-MATTHI	EWS RD	N/A	Ramp inside XWalk1?	N/A	N/A Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None		Road Slope (%)	0.4	N/A Clear Space?	N/A
			Road X Slope (%)	2.2	N/A Clear Space to XWalk (in)	N/A
		N/A	Any Obstructions?	N/A	N/A Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 320	0.00	Obstruction Type		Storm Grate/Utility Type	
				N/A		N/A
					Yes Surface Condition? (G/P)	Good

