

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

6.1

13.0

N/A

Good

Intersection ID: 13362Main Street:BARRINGER\_DRCross Street:WEST\_BVLocation:NEADA ID: 673EB613EC05Ramp Type:PerpInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:42.5

Compliance Description

N/A

No

N/A

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

**Gutter Ponding?** 

Gutter Lip Ht (in)

Painted X Walk1?

X Walk 1 Direction

X Walk 1 Width (in)

X Walk 1 Slope (%)

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)

Road X Slope (%)

Any Obstructions?

**Obstruction Type** 

Flare Traversable LT?

Flare Type LT

## **Codes/Mitigation Info/Possible Solution**

## Field Measurements/Component Compliance

Yes

No

N/A

Yes

Compliance Description

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Storm Grate/Utility Hazard?

Clear Space?

Flare Traversable RT?

Flare Type RT

Data

49.0

35.0

N/A

No

N/A

6.3

5.4

N/A

N/A

N/A

N/A

N/A

To SW



A DESCRIPTION OF THE PROPERTY	
Street 1 Name	BARRINGER DR
Stop Condition-Street 2	StopSign
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solutions:	
Remove & Replace Entire Ramp.	
Oursell Nation	
Surveyor Notes:	
N/A	
DDOW/ADA	
PROW/ADA:	
Not Found, R304.5.1, R304.5.3	

Total Cost:	\$	1850.00

N. Cont.		
	1	
/		



