


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 5384	Main Street: LONG_CREEK_PY	Cross Street: WILLOW_CREST_DR	Location: N
ADA ID: 67485DF1704F	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 26.25

Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance			
	Possible Solutions:				
	Remove & Replace Entire Ramp.	N/A	Ramp Length (in)	43.0	No
		Yes	Ramp Width (in)	53.0	No
		N/A	Flare Type LT	N/A	N/A
		N/A	Flare Slope LT (%)	N/A	N/A
		N/A	Flare Traversable LT?	N/A	N/A
		N/A	Landing Length (in)	N/A	N/A
		N/A	Landing Width (in)	N/A	N/A
		N/A	Landing Slope (%)	N/A	N/A
		N/A	Landing X Slope (%)	N/A	N/A
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R304.2.2, R304.5.3</p>		N/A	Flare Type RT	N/A	N/A
		N/A	Flare Slope RT (%)	N/A	N/A
		N/A	Flare Traversable RT?	N/A	N/A
		N/A	DWS Provided?	N/A	N/A
		N/A	DWS Contrast?	N/A	N/A
		N/A	DWS Length (in)	N/A	N/A
		N/A	DWS Full Width?	N/A	N/A
		N/A	DWS Offset (in)	N/A	N/A
		N/A	Shared Landing?	N/A	N/A
		N/A	Gutter Ponding?	N/A	N/A
		N/A	Gutter Lip Ht (in)	0.5	N/A
		N/A	Painted X Walk1?	No	N/A
			X Walk 1 Direction	To S	N/A
		N/A	X Walk 1 Width (in)	N/A	N/A
			X Walk 1 Slope (%)	1.0	N/A
			X Walk 1 X Slope (%)	4.2	N/A
		N/A	Ramp inside XWalk1?	N/A	N/A
			Road Slope (%)	N/A	N/A
			Road X Slope (%)	N/A	N/A
		N/A	Any Obstructions?	N/A	N/A
<p>Total Cost:</p> <p>\$ 1850.00</p>			Obstruction Type		
				N/A	N/A
				N/A	N/A
			Yes	Surface Condition? (G/P)	Good

