


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 20865	Main Street: SIMSBURY_RD	Cross Street: VALENCIA_TR	Location: NE
ADA ID: 67B3EB86BE38	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 21.25

Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance					
	Possible Solutions:	Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.	N/A	Ramp Length (in)	42.5	Yes	Ramp Slope (%)	5.5
		No	Ramp Width (in)	39.5	No	Ramp XSlope (%)	6.6
		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	Surveyor Notes:	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	PROW/ADA:	N/A	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?
N/A			Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A			Shared Landing?	N/A			
N/A			Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A			Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A			Painted X Walk1?	No	N/A	Painted X Walk2?	No
			X Walk 1 Direction	To W		X Walk 2 Direction	To S
N/A			X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
			X Walk 1 Slope (%)	2.0		X Walk 2 Slope (%)	4.8
			X Walk 1 X Slope (%)	4.6		X Walk 2 X Slope (%)	0.4
Total Cost:	\$ 3200.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
			Road Slope (%)	1.6	N/A	Clear Space?	N/A
			Road X Slope (%)	5.8	N/A	Clear Space to XWalk (in)	N/A
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Obstruction Type			Storm Grate/Utility Type		
			N/A			N/A	
				Yes	Surface Condition? (G/P)	Good	

