

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 12013 Main Street: FREEDOM DR Cross Street: W_MOREHEAD_ST Location: W ADA ID: 67BD998951A7 Ramp Type: Perp Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 22.5

Codes/Mitigation Info/Possible Solution



Street 1 Name	FREEDOM DR
Stop Condition-Street 2	Signal
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solutions: Remove & Replace Entire Ramp. Restripe Crosswalk. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.2.2, R304.5.3

Total Cost: 2050.00

Field Measurements/Component Compliance							
Comp	liance Description	Data	Comp	liance	Description	Data	
N/A	Ramp Length (in)	94.0	No	Ramp	Slope (%)	8.4	
No	Ramp Width (in)	47.0	No	Ramp	XSlope (%)	4.7	
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A	
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A	
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A	
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A	
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A	
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A	
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutte	er Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	er X Slope (%)	N/A	
N/A	Painted X Walk1?	Yes	N/A	Paint	ed X Walk2?	N/A	
	X Walk 1 Direction	To E		X Wa	lk 2 Direction	N/A	
N/A	X Walk 1 Width (in)	114.0	N/A	X Wa	ılk 2 Width (in)	N/A	
	X Walk 1 Slope (%)	5.0		X Wa	lk 2 Slope (%)	N/A	
	X Walk 1 X Slope (%)	2.2		X Wa	lk 2 X Slope (%)	N/A	
N/A	Ramp inside XWalk1?	No	N/A	Ram	o inside XWalk2?	N/A	
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A	
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A	
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A	
	Obstruction Type			Storn	n Grate/Utility Type		
		N/A				N/A	
			Yes	Surfa	ce Condition? (G/P)	Good	





