


Access Compliance Report

Public Rights-of-Way (Curb Ramps)

Intersection ID: 10031406	Main Street: MCALPINE_PARK_DR	Cross Street: N/A	Location: SW
ADA ID: 67D37B25B85B	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No Severity Score: 33.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance							
	Possible Solutions:		Compliance		Description	Data	Compliance		Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A		Ramp Length (in)	67.0	No		Ramp Slope (%)	9.1
			No		Ramp Width (in)	36.0	No		Ramp XSlope (%)	6.0
			N/A		Flare Type LT	N/A	N/A		Flare Type RT	N/A
			N/A		Flare Slope LT (%)	N/A	N/A		Flare Slope RT (%)	N/A
			N/A		Flare Traversable LT?	N/A	N/A		Flare Traversable RT?	N/A
			N/A		Landing Length (in)	N/A	N/A		DWS Provided?	N/A
			N/A		Landing Width (in)	N/A	N/A		DWS Contrast?	N/A
			N/A		Landing Slope (%)	N/A	N/A		DWS Length (in)	N/A
			N/A		Landing X Slope (%)	N/A	N/A		DWS Full Width?	N/A
Surveyor Notes:	N/A		N/A		Landing Curb? (Y/N)	N/A	N/A		DWS Offset (in)	N/A
			N/A		Shared Landing?	N/A				
			N/A		Gutter Ponding?	N/A	N/A		Gutter Slope (%)	N/A
			N/A		Gutter Lip Ht (in)	N/A	N/A		Gutter X Slope (%)	N/A
			N/A		Painted X Walk1?	No	N/A		Painted X Walk2?	No
					X Walk 1 Direction	To NE			X Walk 2 Direction	To NW
			N/A		X Walk 1 Width (in)	N/A	N/A		X Walk 2 Width (in)	N/A
					X Walk 1 Slope (%)	4.1			X Walk 2 Slope (%)	5.0
					X Walk 1 X Slope (%)	1.6			X Walk 2 X Slope (%)	0.5
			N/A		Ramp inside XWalk1?	N/A	N/A		Ramp inside XWalk2?	N/A
				Road Slope (%)	2.8	N/A		Clear Space?	N/A	
				Road X Slope (%)	0.3	N/A		Clear Space to XWalk (in)	N/A	
		N/A		Any Obstructions?	N/A	N/A		Storm Grate/Utility Hazard?	N/A	
				Obstruction Type				Storm Grate/Utility Type		
						N/A			N/A	
							Yes	Surface Condition? (G/P)	Good	

