cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 21352	tersection ID: 21352 Main Street: E_ARROWOOD_RD			Cross	Street:	KINGS_RIDGE_DR	Location:	NE		
ADA ID: 67D60248349C	C Ramp Type: PerpDiag			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	21.25
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
	1-24	Possible Solutions:			Compliance Description		Data Compliance		liance Description	Data
		Remove & Replace Curb	Ramp	o With	N/A	Ramp Length (in)	120.0	Yes	Ramp Slope (%)	6.2
	and the second	Two New Directional Ran	ıps ol	r	No	Ramp Width (in)	42.0	No	Ramp XSlope (%)	6.0
		Equivalent.			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	· A. NATO				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
1 B	-				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	14	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
the second secon	E C				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
NEEDULO	3.11				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
Et d.	1.				N/A	Shared Landing?	N/A			
A CARL	-	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1, R3	04.5.3	6	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
					N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	C. J. all					X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
					N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name KINGS	RIDGE DR					X Walk 1 Slope (%)	1.7		X Walk 2 Slope (%)	0.2
Stop Condition-Street 2	StopSign					X Walk 1 X Slope (%)	0.3		X Walk 2 X Slope (%)	3.3
Street 2 Name E ARRO	OWOOD RD				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None					Road Slope (%)	2.5	N/A	Clear Space?	N/A
						Road X Slope (%)	1.8	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	3200.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A

Yes Surface Condition? (G/P)

Good

