## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 30279 Main Street: HAMPTON_WAY_DR					Cross Street: REAGAN_DR				Location: SE	
ADA ID: 67E68293982E	2E Ramp Type: Combination2				Initial Pass/Fail: Fail Overall Complian				o Severity Score:	10
C	odes/Mitigation Info/	Possible Solution				Field Measure	ments/C	ompo	nent Compliance	
	Possible Solutions:				Compliance Description			Data Compliance Description		
	AS LEN	Remove & Replace Entire Rar		np.	N/A	Ramp Length LT (in)	38.0	N/A	Ramp Length RT (in)	38.5
29 BY-R					N/A	Ramp Width LT (in)	48.0	Yes	Ramp Width RT (in)	48.0
- MUSE	THURSDA				N/A	Ramp Slope LT (%)	1.7	Yes	Ramp Slope RT (%)	7.7
- TANK	M.M. Ser				N/A	Ramp XSlope LT (%)	3.3	No	Ramp XSlope RT (%)	3.4
	2 5				N/A	Ramp Length (in)	46.0	Yes	Ramp Slope (%)	5.0
PEAGAN	S S				No	Ramp Width (in)	39.0	No	Ramp XSlope (%)	3.9
Long -		Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		LT RP < 5%			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
6 8 6					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	PPAL				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	A B				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	I I I DR	Not Found, R304.5.	1. R304.5.3	3	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
TETRICIPALITY IN THE REAL PROVIDENCE				-	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
					N/A	Shared Landing?	N/A			
P 10 11			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
Street 1 Name	StopSign				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	HAMPTON WAY DR				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
Street 2 Name	N/A					X Walk 1 Direction	To W		X Walk 2 Direction	N/A
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
						X Walk 1 Slope (%)	1.1		X Walk 2 Slope (%)	N/A
						X Walk 1 X Slope (%)	1.2		X Walk 2 X Slope (%)	N/A
		Total Cost:	\$	1600.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
						Road Slope (%)	N/A		Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			11 P. 19		- Andreas			N/A	Any Obstruction?	N/A
		A Company of the second				and the second division of the second divisio			Obstruction Type	
										N/A
		7			X			N/A	Storm Grate/Utility Hazard?	N/A

 N/A
 Storm Grate/Utility Hazard?
 N/A

 Storm Grate/Utility Type
 N/A

 Yes
 Surface Condition? (G/P)
 Good

 Curb Slope (%)
 14.6





