


Intersection ID: 10022367		Main Street: CAMFIELD_ST		Cross Street: N/A		Location:		NW											
ADA ID: 6806F668961E		Ramp Type: PerpDiag		Initial Pass/Fail: Fail		Overall Compliance: No		Severity Score: 21.25											
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance															
 <div>Street 1 NameCAMFIELD ST</div> <div>Stop Condition-Street 2None</div> <div>Street 2 NameENTRANCE</div> <div>Stop Condition-Street 1StopSign</div>				Possible Solutions:		Compliance		Description		Data		Compliance		Description		Data			
				Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A		Ramp Length (in)		97.0		No		Ramp Slope (%)		8.6			
						No		Ramp Width (in)		44.5		Yes		Ramp XSlope (%)		0.6			
						N/A		Flare Type LT		N/A		N/A		Flare Type RT		N/A			
						N/A		Flare Slope LT (%)		N/A		N/A		Flare Slope RT (%)		N/A			
						N/A		Flare Traversable LT?		N/A		N/A		Flare Traversable RT?		N/A			
						N/A		Landing Length (in)		N/A		N/A		DWS Provided?		N/A			
						N/A		Landing Width (in)		N/A		N/A		DWS Contrast?		N/A			
						N/A		Landing Slope (%)		N/A		N/A		DWS Length (in)		N/A			
						N/A		Landing X Slope (%)		N/A		N/A		DWS Full Width?		N/A			
<div>Surveyor Notes:</div> <div>N/A</div> <div>PROW/ADA:</div> <div>Not Found, R304.5.1, R304.2.2</div>						N/A		Landing Curb? (Y/N)		N/A		N/A		DWS Offset (in)		N/A			
						N/A		Shared Landing?		N/A									
						N/A		Gutter Ponding?		N/A		N/A		Gutter Slope (%)		N/A			
						N/A		Gutter Lip Ht (in)		N/A		N/A		Gutter X Slope (%)		N/A			
						N/A		Painted X Walk1?		No		N/A		Painted X Walk2?		No			
								X Walk 1 Direction		To S				X Walk 2 Direction		To E			
						N/A		X Walk 1 Width (in)		N/A		N/A		X Walk 2 Width (in)		N/A			
								X Walk 1 Slope (%)		0.9				X Walk 2 Slope (%)		0.7			
								X Walk 1 X Slope (%)		1.7				X Walk 2 X Slope (%)		0.2			
						N/A		Ramp inside XWalk1?		N/A		N/A		Ramp inside XWalk2?		N/A			
<div>Total Cost:</div> <div>\$3200.00</div>								Road Slope (%)		0.2		N/A		Clear Space?		N/A			
								Road X Slope (%)		0.0		N/A		Clear Space to XWalk (in)		N/A			
						N/A		Any Obstructions?		N/A		N/A		Storm Grate/Utility Hazard?		N/A			
								Obstruction Type						Storm Grate/Utility Type					
										N/A						N/A			
										Yes		Surface Condition? (G/P)		Good					

