

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 9940 Main Street: KILDARE\_DR Cross Street: THE\_PLAZA Location: SW

ADA ID: 690797E3DC22 Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 12.5

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

KILDARE DR StopSign THE PLAZA Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

Possible Solutions:

N/A

PROW/ADA:

Not Found, R304.2.2

RE DR pSign LAZA None

Total Cost: \$ 3200.00

9	Complia	nce Description	Data	Compli	ance	Description	Data
1	N/A F	Ramp Length (in)	59.5	No	Ramp	Slope (%)	11.3
١	res F	Ramp Width (in)	48.0	Yes	Ramp	XSlope (%)	0.9
N	N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
1	N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
1	N/A i	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
1	N/A L	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
1	N/A L	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
1	N/A L	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
1	N/A L	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
1	N/A L	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
1	N/A S	Shared Landing?	N/A				
1	N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A
N	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A
1	N/A F	Painted X Walk1?	No	N/A	Painte	ed X Walk2?	No
	)	X Walk 1 Direction	To SE		X Wal	k 2 Direction	To NE
1	N/A	X Walk 1 Width (in)	N/A	N/A	X Wal	k 2 Width (in)	N/A
	)	X Walk 1 Slope (%)	3.7		X Wal	k 2 Slope (%)	2.6
	)	X Walk 1 X Slope (%)	2.5		X Wal	k 2 X Slope (%)	2.7
1	N/A F	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A
	F	Road Slope (%)	1.0	N/A	Clear	Space?	N/A
	F	Road X Slope (%)	7.1	N/A	Clear	Space to XWalk (in)	N/A
1	N/A	Any Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A
	(	Obstruction Type			Storm	Grate/Utility Type	
			N/A				N/A

Surface Condition? (G/P)

Good





