## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



							Leastless	05		
Intersection ID: 50763	Main Street: QUIET_CREEK_CR			Cross	Cross Street: SCOTT_CREEK_DR				Location:	SE
ADA ID: 6909814A4098	8 Ramp Type: Perp			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	10 10 10	Possible Solutions:			Compliance Description			Data Compliance Description		
		Remove & Replace Entit	re Ram	p.	N/A	Ramp Length (in)	47.5	No	Ramp Slope (%)	9.6
	Sist.			•	Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.1
10. 44	Se Sa				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	the deriv				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	- ANTA	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	And the second				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
					N/A	Shared Landing?	N/A			
1/1/ 000	1 1920	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.2.2, R3	04.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
					N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	har					X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
10 m Charles					N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name SCOTT C	REEK DR					X Walk 1 Slope (%)	1.3		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None					X Walk 1 X Slope (%)	1.8		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A

Yes Surface Condition? (G/P)

Good

