

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

44.0

56.0

6.5

2.5

6.4

3.6

N/A

Good N/A

Intersection ID: 10194 Main Street: BURTON_ST Cross Street: SPRING_ST Location: W

ADA ID: 6915F452CB5D Ramp Type: Combination2 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 10


Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
StopSign
Stop Condition-Street 1
BURTON ST
Street 2 Name
N/A
Stop Condition-Street 2
N/A

Total Cost:



N/A

N/A

N/A

N/A

N/A

N/A

N/A

Yes

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Clear Space?

Any Obstruction?

Obstruction Type

Curb Slope (%)







N/A

Ramp inside XWalk1?

Road Slope (%)

1600.00