


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10717	Main Street: N_BREVARD_ST	Cross Street: E_25TH_ST	Location:	N
ADA ID: 69241EE42577	Ramp Type: Perp	Initial Pass/Fail: Pass	Overall Compliance: No	Severity Score: 0

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	70.0	Yes	Ramp Slope (%)	6.8
			Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	0.8
			N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	4.5	Yes	Flare Slope RT (%)	7.8
			N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	Yes
			No	Landing Length (in)	48.0	Yes	DWS Provided?	Yes
			Yes	Landing Width (in)	48.0	Yes	DWS Contrast?	Yes
			No	Landing Slope (%)	3.2	Yes	DWS Length (in)	24.0
			Yes	Landing X Slope (%)	0.0	Yes	DWS Full Width?	Yes
Surveyor Notes:			N/A	Landing Curb? (Y/N)	Yes	Yes	DWS Offset (in)	1.5
PROW/ADA:			N/A	Shared Landing?	No			
Not Found, R304.2.1, R304.2.2-Perp, R304.3.2-Para			Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	2.6
			Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.5
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
				X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
				X Walk 1 Slope (%)	2.7		X Walk 2 Slope (%)	N/A
				X Walk 1 X Slope (%)	0.7		X Walk 2 X Slope (%)	N/A
			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
				Road Slope (%)	N/A	N/A	Clear Space?	Yes
				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
				Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A
						Yes	Surface Condition? (G/P)	Good
Total Cost:		\$	1850.00					

