

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A Main Street: BALLANTYNE_COMMONS_PY Cross Street: N/A							Location:	NW	
ADA ID: 69293A1E5D9B	D9B Ramp Type: Perp				Initial Pass/Fail: Fail Overall Compliance: No				12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	France	Possible Solutions:		Comp	liance Description	Data	Comp	liance Description	Data
	1	Remove & Replace Entire Ran	ıp.	N/A	Ramp Length (in)	64.0	No	Ramp Slope (%)	10.8
	C-		•	Yes	Ramp Width (in)	59.0	Yes	Ramp XSlope (%)	1.8
	- The second second			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
-2 10 - P 56 10-5				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
e e		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
<mark>ह</mark> ्य		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
COMMONS F				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
AND				N/A	Shared Landing?	N/A			
BASS	A.	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
and the second second				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
e.	mont				X Walk 1 Direction	To E		X Walk 2 Direction	N/A
	a starter.			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ENTRANCE				X Walk 1 Slope (%)	1.6		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	3.0		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

