

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Interpretion ID: 29276	Croos S	troot		Logation	NE					
Intersection ID: 28376	Main Street: GEORGIAN_HALL_DR			Cross Street: SOUTHAMPTON_COMMONS_DR					Location:	NE
ADA ID: 6952E9FCFF28 Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description			Data	Data Compliance Description		
and the second s		Remove & Replace Entire R	Ramp.		N/A	Ramp Length (in)	46.0	Yes	Ramp Slope (%)	5.5
	1 de	-			Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	6.3
	N. VI				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	0.//				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	111				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	B/ /				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
Controll controlles	1	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	1. 2.	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
COUNTILLU					N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
Rat	Es A				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	EVA				N/A	Shared Landing?	N/A			
		PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
LAND BA	1	Not Found, R304.5.3			N/A	Gutter Lip Ht (in)	2.0	N/A	Gutter X Slope (%)	N/A
	-			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
						X Walk 1 Direction	To S		X Walk 2 Direction	N/A
Es la				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name SOUTHAMPTON COMMONS DR						X Walk 1 Slope (%)	3.0		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None					X Walk 1 X Slope (%)	5.3		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 18	50.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A

Yes Surface Condition? (G/P)

Good

