

Access Compliance Report Public Rights-of-Way (Curb Ramps)



			•	- /						
Intersection ID: 29321	Main Street: HEWITT_DR			Cross Street: FAIRCREEK_CT					Location:	NE
ADA ID: 695F6E6838EA	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No					o Severity Score:	33.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	E JAC Bart	Possible Solutions:						Compliance Description Data		
	A STAR	Remove & Replace	Entire Ramp	N//		amp Length (in)	48.5	Yes	Ramp Slope (%)	7.2
AAJET	. The same is			No		amp Width (in)	40.5		Ramp XSlope (%)	11.2
	1 1 many			N//		are Type LT	N/A	N/A	Flare Type RT	N/A
	AND AND THE A			N//		are Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N//		are Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	THAT TH			N//		anding Length (in)		N/A	DWS Provided?	N/A
		Surveyor Notes:		N//		anding Width (in)	N/A	N/A	DWS Contrast?	N/A
AL . AL	May Marine	N/A		N//		anding Slope (%)	N/A	N/A	DWS Length (in)	N/A
L HEWITT DR		11/2		N//		anding X Slope (%)	N/A	N/A	DWS Full Width?	N/A
A Contraction of the	A Set of the			N//		anding Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
the section of the section of				N//		nared Landing?	N/A	10,7 1		
	in any	PROW/ADA:		N//		utter Ponding?		N/A	Gutter Slope (%)	N/A
WE STATE AL	in tall			N//		utter Lip Ht (in)	0.5	N/A	Gutter X Slope (%)	N/A
AND AN A COMPANY	1 - 1 - 1	Not Found, R304.	5.1, R304.5.3	N//		ainted X Walk1?		N/A	Painted X Walk2?	N/A
and the second second	all the second			19/2		Walk 1 Direction	To W	IN/A	X Walk 2 Direction	N/A
	State State			NZ						
				N//		Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	FAIRCREEK CT					Walk 1 Slope (%)	4.6		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign					Walk 1 X Slope (%)	8.7		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N//		amp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Ro	oad Slope (%)	N/A	N/A	Clear Space?	N/A
						oad X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N//	A Ar	ny Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 13	850.00	Ot	bstruction Type			Storm Grate/Utility Type	
							N/A			N/A

Yes

Surface Condition? (G/P)

Good





