

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 18091Main Street:ASHLEY_HALL_DRCross Street:IDLEWILD_RDLocation:NEADA ID: 69EAA8E1341FRamp Type:ParaInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:12.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Committee of the commit	
Street 1 Name	IDLEWILD RD
Stop Condition-Street 1	None
Street 2 Name	N/A
Stop Condition-Street 2	N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

LT RP < 5%

PROW/ADA:

R304.3.2

Total Cost: \$ 1600.00

Compliance Description Data				Compliance Description Data		
N/A	Ramp Length LT (in)	86.0	N/A	Ramp Length RT (in)	106.0	
Yes	Ramp Width LT (in)	60.0	Yes	Ramp Width RT (in)	60.0	
Yes	Ramp Slope LT (%)	2.9	No	Ramp Slope RT (%)	9.2	
Yes	Ramp XSlope LT (%)	1.2	Yes	Ramp XSlope RT (%)	1.9	
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	X Walk 1 Direction	To SE		X Walk 2 Direction	N/A	
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
	X Walk 1 Slope (%)	1.6		X Walk 2 Slope (%)	N/A	
	X Walk 1 X Slope (%)	2.8		X Walk 2 X Slope (%)	N/A	
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
	Road Slope (%)	N/A	N/A	Clear Space?	N/A	
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Obstruction Type			Storm Grate/Utility Type		
		N/A			N/A	
			Yes	Surface Condition? (G/P)	Good	
			N/A	Curb Slope (%)	0.9	





