

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

57.5

48.0

3.7

6.6

7.1

6.6

N/A

Main Street: KELVIN PARK CR Intersection ID: 5093 **Cross Street: PENNYCROSS LN** Location: SE **Overall Compliance: No ADA ID: 69EAB3571C5C** Ramp Type: Combination1 Initial Pass/Fail: Fail Severity Score: 21.25

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance

N/A

Yes

Yes

No

Yes

No

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Flare Traversable RT?

Ramp XSlope RT (%)

Data

47.5

36.0

7.5

4.1

74.5

45.5

N/A

No

To W

N/A

4.0

6.2

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

**Gutter Ponding?** 

Gutter Lip Ht (in)

Painted X Walk1?

X Walk 1 Direction

X Walk 1 Width (in)

X Walk 1 Slope (%)

X Walk 1 X Slope (%)

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)



StopSign Street 1 Name **KELVIN PARK CR** Stop Condition-Street 1 N/A Street 2 Name Stop Condition-Street 2 N/A

Possible Solutions: Compliance Description N/A Remove & Replace Entire Ramp. No Yes No N/A No Surveyor Notes: N/A **RT RP < 5%** N/A N/A N/A N/A PROW/ADA: N/A R304.5.1, R304.5.1, R304.5.3 N/A N/A N/A N/A N/A N/A

\$



Total Cost:



1800.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	N/A		Clear Space?	N/A
		Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
TO				N/A	Any Obstruction?	N/A
The state of the s	dear tobac	53			Obstruction Type	
		X				N/A
				N/A	Storm Grate/Utility Hazard?	N/A
					Storm Grate/Utility Type	
						N/A
				Yes	Surface Condition? (G/P)	Good
				J	Curb Slope (%)	N/A