


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10593	Main Street: BEATTIES_FORD_RD	Cross Street: ROZZELLES_FERRY_RD	Location: SE
ADA ID: 6A07699FDEBB	Ramp Type: Combination1	Initial Pass/Fail: Fail	Overall Compliance: No
Severity Score: 33.75			

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length LT (in)	32.0
			Yes	Ramp Width LT (in)	75.0
			No	Ramp Slope LT (%)	8.4
			Yes	Ramp XSlope LT (%)	0.8
			N/A	Ramp Length (in)	68.0
			No	Ramp Width (in)	39.5
	Surveyor Notes:		N/A	Flare Type LT	N/A
	N/A		N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
<p>PROW/ADA:</p> <p>Not Found, R304.5.1, R304.2.2, R304.5.3, R304.3.2</p>			N/A	Landing Length (in)	N/A
			N/A	Landing Width (in)	N/A
			N/A	Landing Slope (%)	N/A
			N/A	Landing X Slope (%)	N/A
			N/A	Landing Curb? (Y/N)	N/A
			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter Lip Ht (in)	N/A
			N/A	Painted X Walk1?	Yes
				X Walk 1 Direction	To NW
<p>Street 1 Name</p> <p>Stop Condition-Street 1</p> <p>Street 2 Name</p> <p>Stop Condition-Street 2</p>				X Walk 1 Width (in)	132.0
				X Walk 1 Slope (%)	2.7
				X Walk 1 X Slope (%)	5.8
			N/A	Ramp inside XWalk1?	Yes
				Road Slope (%)	N/A
				Road X Slope (%)	N/A
			N/A	Clear Space?	N/A
			N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstruction?	N/A
				Obstruction Type	N/A
<p>Total Cost:</p> <p>\$ 1800.00</p>				Storm Grate/Utility Hazard?	N/A
				Storm Grate/Utility Type	N/A
					N/A
			Yes	Surface Condition? (G/P)	Good
				Curb Slope (%)	14.6

