

Intersection ID: 4344		Main Street: MALLARD GROVE RD		Cross Street: POCHARD CT		Location:		NW					
ADA ID: 6A1E1047A27F		Ramp Type: Directional1		Initial Pass/Fail: Fail		Overall Compliance: No		Severity Score: 8.75					
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance									
		Possible Solutions:		Compliance		Description		Data					
		Remove & Replace Entire Ramp.		N/A		Ramp Length (in)		36.0					
				No		Ramp Width (in)		44.5					
				Yes		Ramp Slope (%)		5.3					
				Yes		Ramp XSlope (%)		0.2					
				N/A		Flare Type LT		N/A					
				N/A		Flare Slope LT (%)		N/A					
				N/A		Flare Traversable LT?		N/A					
				N/A		Landing Length (in)		0.0					
				N/A		Landing Width (in)		0.0					
Surveyor Notes:  N/A				N/A		Flare Type RT		N/A					
				N/A		Flare Slope RT (%)		0.0					
				N/A		Flare Traversable RT?		N/A					
				N/A		DWS Provided?		N/A					
				N/A		DWS Contrast?		N/A					
				N/A		DWS Length (in)		N/A					
				N/A		DWS Full Width?		N/A					
				N/A		DWS Offset LT (in)		N/A					
				N/A		DWS Offset RT (in)		N/A					
				N/A		Gutter Slope (%)		N/A					
PROW/ADA:  R304.5.1				N/A		Gutter Lip Ht (in)		0.0					
				N/A		Gutter X Slope (%)		N/A					
				N/A		Painted X Walk1?		No					
						Road Slope (%)		2.0					
						Road X Slope (%)		3.1					
						Clear Space?		N/A					
						Clear Space to XWalk (in)		N/A					
						Storm Grate/Utility Hazard?		N/A					
						Storm Grate/Utility Type							
				N/A		Any Obstructions?		N/A					
Total Cost: \$ 1600.00				Obstruction Type		Yes		Surface Condition? (G/P)		Good			
						N/A		N/A		Curb Slope (%)		N/A	

