

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10027976 Main Street: HARLEE AV				eet:	N/A	Location:	N		
ADA ID: 6A3AF3C9AFF3					ail: Fail Overall C		25		
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
		Possible Solutions:					liance Description	Data	
	12 3	Remove & Replace Entire Ramp		/A	Ramp Length (in)	83.0	Yes	Ramp Slope (%)	5.8
	22:			'es	Ramp Width (in)	48.0	No	Ramp XSlope (%)	7.1
	子		N	/ A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	20		N	I/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	22 :	2	N	I/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		2	N	I/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	22	Surveyor Notes:	N	I/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	A CONTRACT	N/A	N	I/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			Ν	I/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
H H L L H L L H L H L H H H H H H H H H		-	N	I/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
		N	I/A	Shared Landing?	N/A				
OLD DOWD RD		PROW/ADA:	N	I/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
1 1 100		Not Found, R304.5.3	N	/ A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			N	I/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To S		X Walk 2 Direction	N/A
			N	I/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ENTRANCE	-			X Walk 1 Slope (%)	0.2		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	4.5		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A		Ν	I/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			Ν	I/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A		5 5.	N/A

Yes Surface Condition? (G/P)

Good

