cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| Intersection ID: 8203 | Main Str | Main Street: HONEYWOOD_AV | | | TENNESSEE_AV | Location: | W | | |
|--|-----------------|-------------------------------|---|---|-----------------------|-------------------|--------------------------|-----------------------------|------|
| ADA ID: 6A43777E9AE6 | Ramp Ty | Ramp Type: Perp | | | il: Fail Overall (| o Severity Score: | 1.25 | | |
| Codes/Mitigation Info/Possible Solution | | | Field Measurements/Component Compliance | | | | | | |
| | | Possible Solutions: | Compliance Description Date | | | Data | a Compliance Description | | Data |
| 13 | | Remove & Replace Entire Ramp. | N/. | Α | Ramp Length (in) | 49.0 | Yes | Ramp Slope (%) | 5.3 |
| | | | Ye | s | Ramp Width (in) | 48.0 | No | Ramp XSlope (%) | 2.7 |
| | 114 | | N/. | Α | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| | 1 A AN | | N/. | Α | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| USD I | 12005 | | N/. | Α | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| A CONTRACTOR OF | and and a stand | | N/. | Α | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| 12 | | Surveyor Notes: | N/. | Α | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| Service Se | A BALL | N/A | N/. | Α | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| 5 B. | No. Y. | | N/. | Α | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| Lite Slats | | | N/. | Α | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| | | | N/. | Α | Shared Landing? | N/A | | | |
| 23/ 1.1 | 1 300 | PROW/ADA: | N/. | Α | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| | Active | Not Found, R304.5.3 | N /2 | Α | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| | and the second | | N/. | Α | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A |
| | n- Mark | | | | X Walk 1 Direction | To SE | | X Walk 2 Direction | N/A |
| | | | N/. | Α | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| Street 1 Name | HONEYWOOD AV | - | | | X Walk 1 Slope (%) | 3.2 | | X Walk 2 Slope (%) | N/A |
| Stop Condition-Street 2 | StopSign | | | | X Walk 1 X Slope (%) | 1.5 | | X Walk 2 X Slope (%) | N/A |
| Street 2 Name | N/A | | N/. | Α | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| Stop Condition-Street 1 | N/A | | | | Road Slope (%) | N/A | N/A | Clear Space? | N/A |
| | | | | | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A |
| | | | N/ | Α | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | | Total Cost: \$ 1 | 850.00 | | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | | | | N/A | | | N/A |

Yes Surface Condition? (G/P)

Good

