

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 20434	Main Street: COLTSWOOD_CT			Street:	PINEBURR_RD	Location:	SE		
ADA ID: 6A79A2FCD0A6	Ramp Type: BlendTrans2			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	40.0	Yes	BlendTrans Slope (%)	2.5
		Two New Directional Ramps or Equivalent.		Yes	Ramp Width (in)	48.0	No	BlendTrans XSlope (%)	5.2
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
Gon				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
1 B B		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
				N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		NO ENDO		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	A Maria Providence			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
1 110 14				N/A	Shared Landing?	N/A		2110 011001 (11)	
	A I	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
18100	Mary HI	K304.5.5		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	Carlos Carlos			10/4	X Walk 1 Direction	To NE		X Walk 2 Direction	To NW
P/ 7 3	A MARINA				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	COLTSWOOD CT					8.0			5.9
					X Walk 1 Slope (%)	8.0 3.6		X Walk 2 Slope (%)	5.9 6.2
Stop Condition-Street 1 Street 2 Name	StopSign			NI/A	X Walk 1 X Slope (%)		N/A	X Walk 2 X Slope (%)	6.2 N/A
	PINEBURR RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	
Stop Condition-Street 2	None				Road Slope (%)	2.1		Clear Space?	N/A
					Road X Slope (%)	12.2	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A





Yes

N/A

Surface Condition? (G/P)

Curb Slope (%)

Good

4.5