


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: N/A	Main Street: NORTHLAKE CENTRE PY	Cross Street: PROSSER DR	Location: NW
ADA ID: 6AA36DFE86D8	Ramp Type: PerpDiag	Initial Pass/Fail: Pass	Overall Compliance: No
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	

	Possible Solutions:		Compliance		Description	Data	Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A	Ramp Length (in)	96.0	Yes	Ramp Slope (%)	7.7	
			Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	4.7	
			N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A	
			N/A	Flare Slope LT (%)	8.8	N/A	Flare Slope RT (%)	3.2	
			N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No	
			Yes	Landing Length (in)	72.5	Yes	DWS Provided?	Yes	
			Yes	Landing Width (in)	48.0	Yes	DWS Contrast?	Yes	
			No	Landing Slope (%)	2.2	Yes	DWS Length (in)	24.5	
			No	Landing X Slope (%)	6.2	Yes	DWS Full Width?	Yes	
Surveyor Notes:		N/A	N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	2.0	
		N/A	Shared Landing?	No					
PROW/ADA:		Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	3.5		
		Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.4		
		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No		
			X Walk 1 Direction	To S		X Walk 2 Direction	To E		
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
			X Walk 1 Slope (%)	4.1		X Walk 2 Slope (%)	0.5		
			X Walk 1 X Slope (%)	0.6		X Walk 2 X Slope (%)	3.2		
		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
			Road Slope (%)	1.4	N/A	Clear Space?	Yes		
			Road X Slope (%)	2.0	N/A	Clear Space to XWalk (in)	N/A		
		Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No		
			Obstruction Type			Storm Grate/Utility Type			
					N/A		N/A		
					Yes	Surface Condition? (G/P)	Good		
Total Cost:		\$	3200.00						

