

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 44702	tion ID: 44702 Main Street: PATRIOTS_POINT_LN					Location:	NE			
				Cross Street: EAGLES_LANDING_DR						
ADA ID: 6AC7B346AA2C Ramp Type: Perp			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	8.75	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description D			ata Compliance Description		Data	
	and the second second	Remove & Replace Entire Ram	р.	N/A	Ramp Length (in)	47.0	Yes	Ramp Slope (%)	5.1	
				No	Ramp Width (in)	44.0	Yes	Ramp XSlope (%)	0.3	
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
Contraction of the second seco	and the second			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	- matter			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	6.40			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
PANRIOTS POINT IN OF 5		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	A PARTY AND			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
E. E.				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	LAN A			N/A	Shared Landing?	N/A				
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	The second	Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
E The				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	and a second				X Walk 1 Direction	To W		X Walk 2 Direction	N/A	
ation 10 march 10 March		2		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name EAC	GLES LANDING DR				X Walk 1 Slope (%)	3.2		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	0.7		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

