

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

65.0

56.0

5.4

1.9

3.9

1.9

N/A

N/A

N/A

N/A

N/A

15.9

Main Street: N DAVIDSON ST Location: Intersection ID: 10608 **Cross Street: JORDAN PL** SW Initial Pass/Fail: Fail **Overall Compliance: No** 10 ADA ID: 6AFBE81923CD Ramp Type: Combination1 **Severity Score:**

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

Yes

Yes

Yes

Yes

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

Curb Slope (%)

Flare Traversable RT?

Flare Type RT

Ramp XSlope RT (%)

Data

61.0

59.0

4.6

2.4

71.0

46.0

N/A

N/A

N/A

N/A

N/A

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)



Street 1 Name Signal **JORDAN PL** Stop Condition-Street 1 Street 2 Name N/A Stop Condition-Street 2 N/A

Possible Solutions: Compliance Description N/A Remove & Replace Entire Ramp. Yes Yes No N/A No Surveyor Notes: N/A LT RP < 5% N/A N/A N/A N/A PROW/ADA: N/A Not Found, R304.5.1, R304.5.3 N/A N/A N/A N/A N/A

Total Cost:



1800.00

N/A

N/A

	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	Shared Landing?	N/A			
	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
	X Walk 1 Width (in)	111.5		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	2.1		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	0.2		X Walk 2 X Slope (%)	N/A
	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A		Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
	100		N/A	Any Obstruction?	N/A
	III I S. TIMO.			Obstruction Type	
					N/A
			N/A	Storm Grate/Utility Hazard?	N/A
				Storm Grate/Utility Type	14/21
-	THE STATE OF THE S				N/A
			Yes	Surface Condition? (G/P)	Good