

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15785	Main Str	Main Street: CHEROKEE_PL			COLVILLE_RD	Location:	Ν		
ADA ID: 6B29242CE48F	Ramp Ty	Ramp Type: PerpDiag		ass/Fa	ail: Fail Overall C	o Severity Score:	1.25		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	Pr	Possible Solutions:		Compliance Description Data Compliar			liance Description	Data	
		Remove & Replace Curb Ramp \	With	N/A	Ramp Length (in)	70.0	Yes	Ramp Slope (%)	6.4
		Two New Directional Ramps or		Yes	Ramp Width (in)	49.0	No	Ramp XSlope (%)	2.3
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
MI ALL ALL ALL	WAY CON			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	18.10			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	L Vensor 1	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
t.	the second second	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
CHEROKEE PL	E.			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
the second se	K			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
and the second by	LAND MAL			N/A	Shared Landing?	N/A			
him the and have a		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
THE REAL PROPERTY.	a france	Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
A CONTRACTOR OF					X Walk 1 Direction	To S		X Walk 2 Direction	To E
	Star 19 Es			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	CHEROKEE PL	_			X Walk 1 Slope (%)	3.6		X Walk 2 Slope (%)	0.6
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	2.7		X Walk 2 X Slope (%)	2.3
Street 2 Name	COLVILLE RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	2.3	N/A	Clear Space?	N/A
					Road X Slope (%)	2.9	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good



