cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



`````````````````````````````````									
Intersection ID: 29625 Main Street: PLANTERS_ROW_DR				Cross Street: WINGET_RD				Location:	NE
ADA ID: 6B2B1F09DBC3 Ramp Type: PerpDiag			Initial P	nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	35
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	Struge Contraction	Possible Solutions:		Compliance Description		Data Compliance Description		Data	
the state	13 LES LES	Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	176.0	No	Ramp Slope (%)	12.0
		Two New Directional Ramps or		No	Ramp Width (in)	36.0	No	Ramp XSlope (%)	2.7
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
E Contraction of the second				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
B. B.				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	amile 1	1/2		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
E. Alle			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
			N/A	Shared Landing?	N/A	10/4	BWG Gliser (iii)	10/2	
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Not Found, R304.5.1, R304.2.2, R304.5.3				N/A	Painted X Walk1?	N/A No	N/A	Painted X Walk2?	N/A No
				N/A	X Walk 1 Direction	To NW	N/A		To SW
						-		X Walk 2 Direction	
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	PLANTERS ROW DR				X Walk 1 Slope (%)	3.4		X Walk 2 Slope (%)	4.4
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	3.1		X Walk 2 X Slope (%)	3.0
Street 2 Name	WINGET RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	0.9	N/A	Clear Space?	N/A
					Road X Slope (%)	6.0	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

**Yes** Surface Condition? (G/P)

Good

