

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

12.0

60.0

8.0

8.0

6.2

6.2

N/A

No

To E

N/A

1.0

1.6

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Good 20.0

Intersection ID: 45506 Main Street: WADE\_ARDREY\_RD Cross Street: WHEATFIELD\_RD Location: NW
ADA ID: 6B780F3E3910 Ramp Type: Combination1Diag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 0

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 1
Street 2 Name
Stop Condition-Street 2

StopSign WHEATFIELD RD None WADE ARDREY RD Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

Note Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.3

Total Cost:

Compliance Description Data Compliance Description N/A N/A Ramp Length LT (in) 33.0 Ramp Length RT (in) Yes Yes Ramp Width LT (in) 61.0 Ramp Width RT (in) Yes Ramp Slope LT (%) 5.5 Yes Ramp Slope RT (%) Ramp XSlope LT (%) 2.1 Yes Ramp XSlope RT (%) No N/A Ramp Length (in) 92.0 Yes Ramp Slope (%) 48.0 No Ramp XSlope (%) Yes Ramp Width (in) N/A Flare Type LT N/A N/A Flare Type RT N/A N/A N/A Flare Slope LT (%) Flare Slope RT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A Landing Length (in) N/A N/A DWS Provided? N/A N/A **DWS Contrast?** N/A Landing Width (in) N/A Landing Slope (%) N/A N/A DWS Length (in) N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A Shared Landing? N/A N/A Gutter Ponding? N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No Painted X Walk2? To S X Walk 1 Direction X Walk 2 Direction X Walk 1 Width (in) N/A X Walk 2 Width (in) 0.0 X Walk 2 Slope (%) X Walk 1 Slope (%) X Walk 1 X Slope (%) 3.6 X Walk 2 X Slope (%) N/A N/A Ramp inside XWalk1? N/A Ramp inside XWalk2? Road Slope (%) 3.6 Clear Space? Road X Slope (%) 1.7 N/A Clear Space to XWalk (in)

N/A

N/A

Yes

Any Obstruction?

**Obstruction Type** 

Curb Slope (%)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)







3200.00