cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Storm Grate/Utility Type

Surface Condition? (G/P)

Curb Slope (%)

Yes

N/A

Good

12.4

			(/							
Intersection ID: 20441 Main Street: ARCHDALE_DR					Cross Street: OLD_REID_RD				Location: SI			
ADA ID: 6B8E305AC642	Ramp Ty	Ramp Type: Combination2Diag				ail: Fail Overall C	nce: N	o Severity Score:	0			
Codes/Mitigation Info/Possible Solution						Field Measurements/Component Compliance						
	South Mr. St.	Possible Solutions:			Compliance Description		Data Compliance Description		liance Description	Data		
The second la		Remove & Replace	•		N/A	Ramp Length LT (in)	60.5	N/A	Ramp Length RT (in)	N/A		
a the state		Two New Directiona			No	Ramp Width LT (in)	36.0	N/A	Ramp Width RT (in)	N/A		
1 1		Equivalent.			No	Ramp Slope LT (%)	9.0	N/A	Ramp Slope RT (%)	N/A		
					No	Ramp XSlope LT (%)	3.5	N/A	Ramp XSlope RT (%)	N/A		
LA B	a the we				N/A	Ramp Length (in)	36.0	Yes	Ramp Slope (%)	5.1		
ALL	2. A. 4. 13				No	Ramp Width (in)	42.0	No	Ramp XSlope (%)	2.8		
		Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
ALL ALL	Ke - D	N/A			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
	" I sugar				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
B	11913				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
	1 ANICE				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
S S	An All	PROW/ADA: Not Found, R304.5.1, R304.5.1,			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
	MAR HERE			I .	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
		R304.5.3, R304.3.2	,	,	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
					N/A	Shared Landing?	N/A					
	A 6 1				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
Street 1 Name	None				N/A	Gutter Lip Ht (in)	1.0	N/A	Gutter X Slope (%)	N/A		
Stop Condition-Street 1	ARCHDALE DR				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No		
Street 2 Name	StopSign					X Walk 1 Direction	To NE		X Walk 2 Direction	To NW		
Stop Condition-Street 2	OLD REID RD					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A		
						X Walk 1 Slope (%)	4.2		X Walk 2 Slope (%)	8.0		
						X Walk 1 X Slope (%)	4.3		X Walk 2 X Slope (%)	3.3		
		Total Cost:	\$	3200.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
						Road Slope (%)	2.7		Clear Space?	N/A		
						Road X Slope (%)	5.4	N/A	Clear Space to XWalk (in)	N/A		
								N/A	Any Obstruction?	N/A		
		C SACEDO				A CALLER AND			Obstruction Type			
		HT								N/A		
				the brick toright	-			N/A	Storm Grate/Utility Hazard?	N/A		
					feel				Storm Croto/Utility Type	N/A		

