

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

40.0

56.0

12.9

6.6

11.4

1.8

N/A

Intersection ID: 9829 Main Street: CATALINA AV Cross Street: W 26TH ST Ε Location: Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 70 ADA ID: 6BC70EDC34CC Ramp Type: Combination2

Compliance Description

N/A

N/A

N/A

N/A

N/A

No

N/A

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

Gutter Ponding?

Gutter Lip Ht (in)

Painted X Walk1?

X Walk 1 Direction

X Walk 1 Width (in)

X Walk 1 Slope (%)

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance

N/A

Yes

No

No

Nο

Yes

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Flare Traversable RT?

Ramp XSlope RT (%)

Data

40.0

57.0

2.9

2.9

56.5

33.0

N/A

No

N/A

9.9

8.0

N/A

To SW



Street 1 Name StopSign Stop Condition-Street 1 **W 26TH ST** N/A Street 2 Name Stop Condition-Street 2 N/A Possible Solutions: Remove & Replace Entire Ramp. Surveyor Notes: NO CURB LINE, LT RP < 5% PROW/ADA: R304.5.1, R304.2.2, R304.3.2, R304.5.3, R302.7

Total Cost:



1600.00

