

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 4298	Main St	Cross Street: TWIN_DR					Location:	SE	
ADA ID: 6BC9B0F87049	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	C. ASSA LET . Auto a	Possible Solutions:					Data Compliance Description		
		Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	62.0	No	Ramp Slope (%)	10.6
	1	· · · · · · · · · · · · · ·		Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	3.4
		PP 的		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Contractor Contractor	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	A Start Start	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		8		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
		¥		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
E CALLER AND		Not Found, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	A AND - A			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To W		X Walk 2 Direction	N/A
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	OLD STATESVILLE RD				X Walk 1 Slope (%)	1.0		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	3.5		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$1	850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

