

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 31756	Main Street: FIRST_RUN_CT	Cross Street: PAPER_BIRCH_DR	Location: NE
ADA ID: 6C648B7AE564	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 21.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		No	Ramp Length (in)	96.0
			No	Ramp Width (in)	37.0
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Landing Length (in)	N/A
			N/A	Landing Width (in)	N/A
			N/A	Landing Slope (%)	N/A
			N/A	Landing X Slope (%)	N/A
Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.2.2			N/A	Flare Type RT	N/A
			N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable RT?	N/A
			N/A	DWS Provided?	N/A
			N/A	DWS Contrast?	N/A
			N/A	DWS Length (in)	N/A
			N/A	DWS Full Width?	N/A
			N/A	DWS Offset (in)	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter Lip Ht (in)	N/A
Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1			No	Painted X Walk1?	No
			To W	X Walk 1 Direction	To S
			N/A	X Walk 1 Width (in)	N/A
			2.6	X Walk 1 Slope (%)	1.2
			0.0	X Walk 1 X Slope (%)	1.1
			N/A	Ramp inside XWalk1?	N/A
			0.9	Road Slope (%)	N/A
			2.9	Road X Slope (%)	N/A
			N/A	Any Obstructions?	N/A
				Obstruction Type	
Total Cost:			\$ 3200.00		
			N/A		N/A
			Yes	Surface Condition? (G/P)	Good

