

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11731 Main Street: E_W_T_HARRIS_BV Cross Street: GROVE_PARK_BV Location: E

ADA ID: 6C6CF30C6219 Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 13.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

GROVE PARK BV StopSign E W T HARRIS BV None Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.2.2, R304.5.3

Total Cost: \$ 3200.00

	Field Measure	ements/C	<u>ompo</u>	nent Compliar	nce	
Compliance Description		Data	Compliance Description		Data	
N/A	Ramp Length (in)	61.0	No	Ramp Slope (%)	9.7
Yes	Ramp Width (in)	48.0	No	Ramp XSlope (9	%)	3.2
N/A	Flare Type LT	N/A	N/A	Flare Type RT		N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT	(%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversab	le RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?)	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?		N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width	?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)		N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope	(%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk	2?	No
	X Walk 1 Direction	To NW		X Walk 2 Directi	ion	To SW
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width	(in)	N/A
	X Walk 1 Slope (%)	0.4		X Walk 2 Slope	(%)	2.7
	X Walk 1 X Slope (%)	4.0		X Walk 2 X Slop	oe (%)	0.3
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XV	Valk2?	N/A
	Road Slope (%)	2.8	N/A	Clear Space?		N/A
	Road X Slope (%)	0.7	N/A	Clear Space to	XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Uti	lity Hazard?	N/A
	Obstruction Type		l	Storm Grate/Uti	lity Type	
		N/A				N/A

Yes

Surface Condition? (G/P)

Good





