cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



ntersection ID: 4672 Main Street: W_MALLARD_CREEK_CHURCl6ress Street: SENATOR_ROYALL_DR							Location:	NE	
ADA ID: 6D2A950FA994 Ramp T	ID: 6D2A950FA994 Ramp Type: IslandPerp			il: Fail Overall	o Severity Score:	26.25			
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	Possible Solutions:	Compliance Description			Data Compliance Description			Data	
UT MEALE MARKAN	Remove & Replace Entire Ramp.	. I	N/A	Ramp Length (in)	59.0	No	Ramp Slope (%)	16.3	
			/es	Ramp Width (in)	48.0	No	Ramp XSlope (%)	4.8	
		Ν	I/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
		N	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
		١	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
		١	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
A A A	Surveyor Notes:	١	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	N/A	N	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
		١	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
WI MALLARD ORIER COMPOSE		١	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
A MANAGARAN OR AND A MANAGARAN		١	N/A	Shared Landing?	N/A				
TA T BALL	PROW/ADA:	N	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
The second se	R304.2.2, R304.5.3	N	I/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
6. C	, , , , , , , , , , , , , , , , , , , ,	N	N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
a find the provide the				X Walk 1 Direction	To SW		X Walk 2 Direction	N/A	
		1	N/A	X Walk 1 Width (in)	107.0	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name W MALLARD CREEK CHURCH RD	-			X Walk 1 Slope (%)	5.1		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2 Signal				X Walk 1 X Slope (%)	4.5		X Walk 2 X Slope (%)	N/A	
Street 2 Name N/A		1	N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1 N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
,				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
		1	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Total Cost: \$ 3	400.00		Obstruction Type			Storm Grate/Utility Type		
	······ • •				N/A			N/A	
						Yes	Surface Condition? (G/P)	Good	

2 2 2 1