


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10037884	Main Street: SHARON_VIEW_RD	Cross Street: N/A	Location: SW
ADA ID: 6D64A99B883F	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 8.75	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance			
	Possible Solutions:		Compliance	Description	Data	
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A	Ramp Length (in)	68.0	Yes
			No	Ramp Width (in)	47.0	Yes
			N/A	Flare Type LT	N/A	N/A
			N/A	Flare Slope LT (%)	N/A	N/A
			N/A	Flare Traversable LT?	N/A	N/A
			N/A	Landing Length (in)	N/A	N/A
			N/A	Landing Width (in)	N/A	N/A
			N/A	Landing Slope (%)	N/A	N/A
			N/A	Landing X Slope (%)	N/A	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A
			N/A	Shared Landing?	N/A	
			N/A	Gutter Ponding?	N/A	N/A
			N/A	Gutter Lip Ht (in)	1.0	N/A
			N/A	Painted X Walk1?	No	N/A
				X Walk 1 Direction	To E	
			N/A	X Walk 1 Width (in)	N/A	N/A
				X Walk 1 Slope (%)	1.0	
				X Walk 1 X Slope (%)	2.1	
			N/A	Ramp inside XWalk1?	N/A	N/A
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>R304.5.1</p>						
				Road Slope (%)	1.3	N/A
				Road X Slope (%)	0.4	N/A
			N/A	Any Obstructions?	N/A	N/A
				Obstruction Type		
					N/A	N/A
					Yes	Surface Condition? (G/P)
						Good
Street 1 Name	ENTRANCE					
Stop Condition-Street 2	None					
Street 2 Name	SHARON VIEW RD					
Stop Condition-Street 1	None					
Total Cost:	\$	3200.00				

