


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 7519	Main Street: TRIBUNE_DR	Cross Street: AMOS_HOARD_RD	Location: W
ADA ID: 6DA03BD18618	Ramp Type: Perp	Initial Pass/Fail: Pass	Overall Compliance: No
			Severity Score: 20.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		<b>Compliance</b>	<b>Description</b>	<b>Data</b>
	<b>Remove &amp; Replace Entire Ramp.</b>		<b>Compliance</b>	<b>Description</b>	<b>Data</b>
			N/A	Ramp Length (in)	97.0
			Yes	Ramp Width (in)	48.0
			N/A	Flare Type LT	Sloped
			N/A	Flare Slope LT (%)	3.8
			N/A	Flare Traversable LT?	Yes
			No	Landing Length (in)	N/A
			No	Landing Width (in)	N/A
			No	Landing Slope (%)	N/A
<p>Surveyor Notes:</p> <p><b>N/A</b></p> <p>PROW/ADA:</p> <p><b>Not Found, R304.5.3, R304.2.1, R304.2.2-Perp, R304.3.2-Para, R305</b></p>			Yes	Flare Slope RT (%)	8.0
			N/A	Flare Traversable RT?	Yes
			No	DWS Provided?	No
			No	DWS Contrast?	No
			No	DWS Length (in)	N/A
			No	DWS Full Width?	No
			N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	No
			Yes	Gutter Ponding?	No
			Yes	Gutter Lip Ht (in)	0.0
<p>Street 1 Name</p> <p>Stop Condition-Street 2</p> <p>Street 2 Name</p> <p>Stop Condition-Street 1</p>			N/A	Painted X Walk1?	No
				X Walk 1 Direction	To NE
			N/A	X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	3.9
				X Walk 1 X Slope (%)	2.5
			N/A	Ramp inside XWalk1?	N/A
				Road Slope (%)	N/A
				Road X Slope (%)	N/A
			Yes	Any Obstructions?	No
				Obstruction Type	
<p>Total Cost:</p> <p>\$ 1850.00</p>			N/A	Clear Space?	Yes
				Clear Space to XWalk (in)	N/A
			Yes	Storm Grate/Utility Hazard?	No
				Storm Grate/Utility Type	
			N/A		N/A
			Yes	Surface Condition? (G/P)	Good

