

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

6.8

5.2

N/A

Intersection ID: 25775 Main Street: CARMEL RD Cross Street: PINEVILLE-MATTHEWS RD Location: SW ADA ID: 6DBF2EA82F4C Ramp Type: IslandPerp Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 21.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

No

N/A

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Data

96.0

40.0

N/A



PINEVILLE-MATTHEWS RD Street 1 Name Stop Condition-Street 2 None N/A Street 2 Name Stop Condition-Street 1 N/A

Possible Solutions:	Compliance Description
Remove & Replace Entire Ramp.	N/A Ramp Length (in)
·	No Ramp Width (in)
	N/A Flare Type LT
	N/A Flare Slope LT (%)
	N/A Flare Traversable L
	N/A Landing Length (in
Surveyor Notes:	N/A Landing Width (in)
N/A	N/A Landing Slope (%)
	N/A Landing X Slope (%
	N/A Landing Curb? (Y/N
	N/A Shared Landing?
PROW/ADA:	N/A Gutter Ponding?
Not Found, R304.5.1, R304.5.3	N/A Gutter Lip Ht (in)
	N/A Painted X Walk1?
	X Walk 1 Direction
N/A	N/A X Walk 1 Width (in)
	X Walk 1 Slope (%
	X Walk 1 X Slope (
	N/A Ramp inside XWall
	Road Slone (%)



Total Cost:



3400.00



N/A Flare Slope LT (%) N/A N/A Flare Slope RT (%) N/A N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A Landing Length (in) N/A N/A DWS Provided? N/A N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A N/A Landing Slope (%) DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A N/A Painted X Walk1? Yes N/A Painted X Walk2? N/A X Walk 1 Direction To SW X Walk 2 Direction N/A N/A X Walk 1 Width (in) 118.0 X Walk 2 Width (in) N/A X Walk 1 Slope (%) 0.2 X Walk 2 Slope (%) N/A X Walk 2 X Slope (%) X Walk 1 X Slope (%) 5.1 N/A N/A N/A Ramp inside XWalk2? Ramp inside XWalk1? Yes N/A Road Slope (%) N/A N/A Clear Space? N/A Road X Slope (%) N/A N/A Clear Space to XWalk (in) N/A N/A N/A Any Obstructions? N/A Storm Grate/Utility Hazard? N/A **Obstruction Type** Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good