

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



| Intersection ID: 8932                   | Main St      | Main Street: JENNINGS_ST      |                                         |   | RUSSELL AV                                     | Location: | SE   |                             |      |
|-----------------------------------------|--------------|-------------------------------|-----------------------------------------|---|------------------------------------------------|-----------|------|-----------------------------|------|
| ADA ID: 6DE3F5FB4C55                    |              | Ramp Type: Perp               |                                         |   | Initial Pass/Fail: Fail Overall Compliance: No |           |      |                             | 12.5 |
| Codes/Mitigation Info/Possible Solution |              |                               |                                         |   |                                                |           |      |                             |      |
|                                         |              |                               | Field Measurements/Component Compliance |   |                                                |           |      |                             |      |
|                                         | -11-         | Possible Solutions:           | Compliance Description                  |   | Data Compliance Description                    |           | Data |                             |      |
| A The A                                 | A Carl       | Remove & Replace Entire Ramp. |                                         |   | Ramp Length (in)                               | 59.5      | No   | Ramp Slope (%)              | 9.7  |
|                                         | i findi      |                               | Yes                                     |   | Ramp Width (in)                                | 48.0      | Yes  | Ramp XSlope (%)             | 0.8  |
| tout 1 states and and                   |              |                               | N/A                                     |   | Flare Type LT                                  | N/A       | N/A  | Flare Type RT               | N/A  |
| Notice Stations                         | TABLE N      |                               | N/#                                     | 4 | Flare Slope LT (%)                             | N/A       | N/A  | Flare Slope RT (%)          | N/A  |
| - the start of the start                |              | 8                             | N/#                                     | 4 | Flare Traversable LT?                          | N/A       | N/A  | Flare Traversable RT?       | N/A  |
| 5 & RUSSELL                             | <b>W</b>     | -                             | N/#                                     | 4 | Landing Length (in)                            | N/A       | N/A  | DWS Provided?               | N/A  |
|                                         | 1            | Surveyor Notes:               | N/#                                     | 4 | Landing Width (in)                             | N/A       | N/A  | DWS Contrast?               | N/A  |
| દા <mark>કે</mark> દિ                   |              | N/A                           | N/A                                     | 4 | Landing Slope (%)                              | N/A       | N/A  | DWS Length (in)             | N/A  |
|                                         | N" MARA      |                               | N/#                                     | 4 | Landing X Slope (%)                            | N/A       | N/A  | DWS Full Width?             | N/A  |
| State State                             |              | 2                             | N/#                                     | 4 | Landing Curb? (Y/N)                            | N/A       | N/A  | DWS Offset (in)             | N/A  |
|                                         |              |                               | N/A                                     | 4 | Shared Landing?                                | N/A       |      |                             |      |
|                                         | Sala Pro sag | PROW/ADA:                     | N/#                                     | 4 | Gutter Ponding?                                | N/A       | N/A  | Gutter Slope (%)            | N/A  |
|                                         |              | Not Found, R304.2.2           | N/A                                     | 4 | Gutter Lip Ht (in)                             | N/A       | N/A  | Gutter X Slope (%)          | N/A  |
|                                         |              | ······                        | N/A                                     | 4 | Painted X Walk1?                               | No        | N/A  | Painted X Walk2?            | N/A  |
|                                         | A PERMIT     |                               |                                         |   | X Walk 1 Direction                             | To W      |      | X Walk 2 Direction          | N/A  |
|                                         | a the second |                               | N/A                                     | 4 | X Walk 1 Width (in)                            | N/A       | N/A  | X Walk 2 Width (in)         | N/A  |
| Street 1 Name                           | JENNINGS ST  | -                             |                                         |   | X Walk 1 Slope (%)                             | 2.0       |      | X Walk 2 Slope (%)          | N/A  |
| Stop Condition-Street 2                 | StopSign     |                               |                                         |   | X Walk 1 X Slope (%)                           | 0.6       |      | X Walk 2 X Slope (%)        | N/A  |
| Street 2 Name                           | N/A          |                               | N/A                                     |   | Ramp inside XWalk1?                            | N/A       | N/A  | Ramp inside XWalk2?         | N/A  |
| Stop Condition-Street 1                 | N/A          |                               |                                         |   | Road Slope (%)                                 | N/A       | N/A  | Clear Space?                | N/A  |
|                                         |              |                               |                                         |   | Road X Slope (%)                               | N/A       | N/A  | Clear Space to XWalk (in)   | N/A  |
|                                         |              |                               | N/A                                     |   | Any Obstructions?                              | N/A       | N/A  | Storm Grate/Utility Hazard? | N/A  |
|                                         |              | Total Cost: \$ 1              | 850.00                                  |   | Obstruction Type                               | N/A       |      | Storm Grate/Utility Type    | 11/2 |
|                                         |              |                               | 000.00                                  |   | Obstruction Type                               | NI/A      |      | Storm Grate/Otility Type    |      |
|                                         |              |                               |                                         |   |                                                | N/A       |      |                             | N/A  |

Yes Surface Condition? (G/P)

Good

