## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



|  |          |  |         |  |                       |      |                             | Lesstian                    |      |
|--|----------|--|---------|--|-----------------------|------|-----------------------------|-----------------------------|------|
| Intersection ID: 10011741 Main Street: N_SHARON_AMITY_RD |          |  |         | ross Street: N/A                             |                       |      |                             | Location:                   | NE   |
| ADA ID: 6E51B5216B12 Ramp Type: PerpDiag                 |          |  | Initial | itial Pass/Fail: Fail Overall Compliance: No |                       |      |                             | o Severity Score:           | 22.5 |
| Codes/Mitigation Info/Possible Solution                  |          |  |         | Field Measurements/Component Compliance      |                       |      |                             |                             |      |
|  |          | Possible Solutions:                        |         | Compliance Description                       |                       |      | Data Compliance Description |                             | Data |
|  |          | Remove & Replace Curb Ramp                 | With    | N/A  | Ramp Length (in)      | 60.0 | No                          | Ramp Slope (%)              | 9.6  |
|  |          | Two New Directional Ramps or               |         | No   | Ramp Width (in)       | 36.0 | No                          | Ramp XSlope (%)             | 4.0  |
|  |          | Equivalent.                                |         | N/A  | Flare Type LT         | N/A  | N/A                         | Flare Type RT               | N/A  |
|  |          |  |         | N/A  | Flare Slope LT (%)    | N/A  | N/A                         | Flare Slope RT (%)          | N/A  |
|  |          |  |         | N/A  | Flare Traversable LT? | N/A  | N/A                         | Flare Traversable RT?       | N/A  |
|  |          |  |         | N/A  | Landing Length (in)   | N/A  | N/A                         | DWS Provided?               | N/A  |
|  |          | Surveyor Notes:                            |         | N/A  | Landing Width (in)    | N/A  | N/A                         | DWS Contrast?               | N/A  |
|  |          | N/A  |         | N/A  | Landing Slope (%)     | N/A  | N/A                         | DWS Length (in)             | N/A  |
|  |          |  |         | N/A  | Landing X Slope (%)   | N/A  | N/A                         | DWS Full Width?             | N/A  |
|  |          |  |         | N/A  | Landing Curb? (Y/N)   | N/A  | N/A                         | DWS Offset (in)             | N/A  |
| a 🖏 🚆 🕹  | r al     |  |         | N/A  | Shared Landing?       | N/A  |                             |                             |      |
|  |          | PROW/ADA:                                  |         | N/A  | Gutter Ponding?       | N/A  | N/A                         | Gutter Slope (%)            | N/A  |
|  |          | Not Found, R304.5.1, R304.2.2,<br>R304.5.3 |         | N/A  | Gutter Lip Ht (in)    | N/A  | N/A                         | Gutter X Slope (%)          | N/A  |
|  |          |  |         | N/A  | Painted X Walk1?      | No   | N/A                         | Painted X Walk2?            | No   |
|  |          |  |         |  | X Walk 1 Direction    | To W |                             | X Walk 2 Direction          | To S |
|  |          |  |         | N/A  | X Walk 1 Width (in)   | N/A  | N/A                         | X Walk 2 Width (in)         | N/A  |
| Street 1 Name N SHARON                                   | AMITY RD |  |         |  | X Walk 1 Slope (%)    | 1.9  |                             | X Walk 2 Slope (%)          | 1.3  |
| Stop Condition-Street 2                                  | None     |  |         |  | X Walk 1 X Slope (%)  | 0.5  |                             | X Walk 2 X Slope (%)        | 4.4  |
| Street 2 Name  | ENTRANCE |  |         | N/A  | Ramp inside XWalk1?   | N/A  | N/A                         | Ramp inside XWalk2?         | N/A  |
| Stop Condition-Street 1                                  | None     |  |         |  | Road Slope (%)        | 0.7  | N/A                         | Clear Space?                | N/A  |
|  |          |  |         |  | Road X Slope (%)      | 2.8  | N/A                         | Clear Space to XWalk (in)   | N/A  |
|  |          |  |         | N/A  | Any Obstructions?     | N/A  | N/A                         | Storm Grate/Utility Hazard? | N/A  |
|  |          | Total Cost: \$                             | 3200.00 |  | Obstruction Type      |      |                             | Storm Grate/Utility Type    |      |
|  |          |  |         |  |                       | N/A  |                             |                             | N/A  |

Yes Surface Condition? (G/P)

Good

