


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 11227	Main Street: N_GRAHAM_ST	Cross Street: NC_MUSIC_FACTORY_BV	Location: NW
ADA ID: 6E59E227A011	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 12.5	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance							
	Possible Solutions:		Compliance		Description	Data	Compliance		Description	Data
	Remove & Replace Entire Ramp.		N/A		Ramp Length (in)	72.0	No		Ramp Slope (%)	9.0
			Yes		Ramp Width (in)	48.0	Yes		Ramp XSlope (%)	1.2
			N/A		Flare Type LT	N/A	N/A		Flare Type RT	N/A
			N/A		Flare Slope LT (%)	N/A	N/A		Flare Slope RT (%)	N/A
			N/A		Flare Traversable LT?	N/A	N/A		Flare Traversable RT?	N/A
			N/A		Landing Length (in)	N/A	N/A		DWS Provided?	N/A
			N/A		Landing Width (in)	N/A	N/A		DWS Contrast?	N/A
			N/A		Landing Slope (%)	N/A	N/A		DWS Length (in)	N/A
			N/A		Landing X Slope (%)	N/A	N/A		DWS Full Width?	N/A
Surveyor Notes:	N/A		N/A		Landing Curb? (Y/N)	N/A	N/A		DWS Offset (in)	N/A
			N/A		Shared Landing?	N/A				
			N/A		Gutter Ponding?	N/A	N/A		Gutter Slope (%)	N/A
			N/A		Gutter Lip Ht (in)	N/A	N/A		Gutter X Slope (%)	N/A
			N/A		Painted X Walk1?	Yes	N/A		Painted X Walk2?	N/A
					X Walk 1 Direction	To S			X Walk 2 Direction	N/A
			N/A		X Walk 1 Width (in)	114.0	N/A		X Walk 2 Width (in)	N/A
					X Walk 1 Slope (%)	3.9			X Walk 2 Slope (%)	N/A
					X Walk 1 X Slope (%)	0.8			X Walk 2 X Slope (%)	N/A
			N/A		Ramp inside XWalk1?	Yes	N/A		Ramp inside XWalk2?	N/A
PROW/ADA:	Not Found, R304.2.2				Road Slope (%)	N/A	N/A		Clear Space?	N/A
					Road X Slope (%)	N/A	N/A		Clear Space to XWalk (in)	N/A
			N/A		Any Obstructions?	N/A	N/A		Storm Grate/Utility Hazard?	N/A
					Obstruction Type				Storm Grate/Utility Type	
							N/A			N/A
							Yes		Surface Condition? (G/P)	Good
	Total Cost:		\$	1850.00						

