

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Interpretion ID: 50764	64 Main Street: LAZY_CREEK_LN			oti		Location	N		
Intersection ID: 50764	wain Str	Cross Street: QUIET_CREEK_CR					Location:	N	
ADA ID: 6E7622CBDF9F Ramp Type: Perp		Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75		
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
		Possible Solutions:	Compliance Description			Data	Data Compliance Description		
and the second		Remove & Replace Entire Ramp.	N/#	Α	Ramp Length (in)	46.5	No	Ramp Slope (%)	9.6
			Yes	S	Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.5
			N/A	A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	1		N/#	Α	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Α	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Α	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	. 5	Surveyor Notes:	N/A	Α	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A	N/A	Α	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
the second second			N/A	Α	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
A A A A A A A A A A A A A A A A A A A	Sur 1		N/A	Α	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
TELE CONTRACTOR	24		N/A	Α	Shared Landing?	N/A			
The Case	1. Alton	PROW/ADA:	N/A	Α	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	the set	R304.2.2, R304.5.3	N/A	A	Gutter Lip Ht (in)	1.5	N/A	Gutter X Slope (%)	N/A
		,	N/A	Α	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
TA THE CONTROL OF	1 1				X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
			N/#	Α	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name LAZY C	REEK LN				X Walk 1 Slope (%)	0.7		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	0.7		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A		N/#	Α	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N//	Α	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 1	850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

**Yes** Surface Condition? (G/P)

Good

