

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

| Intersection ID: 53502 Main Str | | treet: WRIGHT_HILL_RD | | Cross Street: BERKELEY_PLACE_DR | | | | Location: | NE |
|---|--|---|---------|---|-----------------------|------|-----------------------------|-----------------------------|------|
| ADA ID: 6EBE65EBFE | BE65EBFB24 Ramp Type: PerpDiag | | Initial | Initial Pass/Fail: Fail Overall Compliance: I | | | | o Severity Score: | 12.5 |
| Codes/Mitigation Info/Possible Solution | | | | Field Measurements/Component Compliance | | | | | |
| | and the second s | Possible Solutions: | | Compliance Description | | Data | Data Compliance Description | | Data |
| | | Remove & Replace Curb Ramp W Two New Directional Ramps or Equivalent. | n With | N/A | Ramp Length (in) | 47.5 | No | Ramp Slope (%) | 8.9 |
| Mal min at | | | • | Yes | Ramp Width (in) | 72.5 | Yes | Ramp XSlope (%) | 0.8 |
| ₽ / / ₽ | | | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| | | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| | | | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| | 1 | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| | La Carte Carta Car | | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| <u>ج</u> ک | | N/A | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| A DECEMBER OF A | All an an an an an | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| EERKIELEY PLACE DR | | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| | | | | N/A | Shared Landing? | N/A | | | |
| | | | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| The second second | N/A | R304.2.2 | | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| and and a | | 10011212 | | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | No |
| ATTIN HAR SHE | | | | | X Walk 1 Direction | To W | | X Walk 2 Direction | To S |
| | 12011 文书 | | | N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| Street 1 Name | WRIGHT HILL RD | - | | | X Walk 1 Slope (%) | 2.4 | | X Walk 2 Slope (%) | 2.1 |
| Stop Condition-Street 2 | StopSign | | | | X Walk 1 X Slope (%) | 3.5 | | X Walk 2 X Slope (%) | 0.6 |
| Street 2 Name | BERKELEY PLACE DR | | | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| Stop Condition-Street 1 | None | | | | Road Slope (%) | 2.4 | N/A | Clear Space? | N/A |
| | | | | | Road X Slope (%) | 2.1 | N/A | Clear Space to XWalk (in) | N/A |
| | | | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | | Total Cost: \$ | 3200.00 | | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | | | | N/A | | | N/A |
| | | | | | | | 1 | | |