


Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A Main Street: S BREVARD ST **Cross Street: E 3RD ST** Location: N ADA ID: 6EC42649D8C3 Ramp Type: Perp Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 10

Codes/Mitigation Info/Possible Solution



E 3RD ST Street 1 Name Stop Condition-Street 2 Signal Street 2 Name N/A Stop Condition-Street 1 N/A Possible Solutions: Remove & Replace Entire Ramp. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.5.3

Total Cost: 1850.00

Field Measurements/Component Compliance						
Compliance Description		Data	Comp	liance	Description	Data
N/A	Ramp Length (in)	62.0	Yes	Ramp	Slope (%)	6.5
No	Ramp Width (in)	44.0	No	Ramp	XSlope (%)	2.5
N/A	Flare Type LT	N/A	N/A	Flare ⁻	Гуре RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N/A	Flare Traversable LT?	No	N/A	Flare ⁻	Traversable RT?	No
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter	Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter	X Slope (%)	N/A
N/A	Painted X Walk1?	Yes	N/A	Painte	d X Walk2?	N/A
	X Walk 1 Direction	To SW		X Wall	k 2 Direction	N/A
N/A	X Walk 1 Width (in)	103.0	N/A	X Wall	k 2 Width (in)	N/A
	X Walk 1 Slope (%)	2.1		X Wall	k 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	0.4		X Wall	k 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp	inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A
	Obstruction Type			Storm	Grate/Utility Type	
		N/A				N/A
			Yes	Surfac	e Condition? (G/P)	Good
	V					





