


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 10020374	Main Street: BALLANTYNE CORPORATE PL	Cross Street: N/A	Location: S
ADA ID: 6EDF318A39D4	Ramp Type: Directional	Initial Pass/Fail: Fail	Overall Compliance: No
Severity Score: 1.25			
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	

	Possible Solutions:				
	Remove & Replace Entire Ramp.				
	Surveyor Notes:				
	N/A				
	PROW/ADA:				
	R304.5.3				
	Street 1 Name	ENTRANCE			
	Stop Condition-Street 1	StopSign			
	Street 2 Name	N/A			
	Stop Condition-Street 2	N/A			
Total Cost:		\$	1600.00		
				Compliance	Description
				Data	
				Compliance	Description
				Data	
				N/A	Grade Break?
				N/A	Grade Break Slope (%)
				N/A	Grade Break XSlope (%)
				N/A	Flare Type LT
				N/A	Flare Slope LT (%)
				N/A	Flare Traversable LT?
				N/A	Flare Traversable RT?
				N/A	Landing Length (in)
				N/A	Landing Width (in)
				N/A	Landing Slope (%)
				N/A	Landing X Slope (%)
				N/A	Landing Curb? (Y/N)
				N/A	Shared Landing?
				N/A	Gutter Ponding?
				N/A	Gutter Lip Ht (in)
				N/A	Painted X Walk1?
				N/A	Ramp inside XWalk1?
				N/A	Any Obstructions?
				N/A	Obstruction Type
				N/A	Surface Condition? (G/P)
				N/A	Curb Slope (%)

