cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 27419	ection ID: 27419 Main Street: WILLIAMS_POND_LN				Cross Street: WILLOWS_WISP_DR			
							Location:	12.5
ADA ID: 6F06E7FF8F39 Ramp Type: PerpDiag		initial P	nitial Pass/Fail: Fail Overall Compliance: No					12.5
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
Entreme as a second sec	Possible Solutions:		Compliance Description		Data Compliance Descri		liance Description	iption Data
	Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	97.0	Yes	Ramp Slope (%)	7.3
	Two New Directional Ramps or		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	5.3
	Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	a the second sec		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
the state of the s	3		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A			
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	1 to a los		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
Contraction of the second second	a de		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name WILLOWS W	ISP DR			X Walk 1 Slope (%)	1.2		X Walk 2 Slope (%)	9.5
Stop Condition-Street 2 Sto	opSign			X Walk 1 X Slope (%)	4.7		X Walk 2 X Slope (%)	0.7
Street 2 Name WILLIAMS PC	DND LN		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 Sto	opSign			Road Slope (%)	2.7	N/A	Clear Space?	N/A
				Road X Slope (%)	5.8	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A

Yes Surface Condition? (G/P)

Good

