cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A	Main Street: ENDHAVEN_LN		Cross Street: MEGWOOD_DR				Location:	SW	
ADA ID: 6F22F2FB0D0A	Ramp Ty	/pe: PerpDiag	Initial Pass/	nitial Pass/Fail: Pass Overall Compliance: No			o Severity Score:	10.25	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
The second second		Possible Solutions:	Con	Compliance Description Dat				Data	
		Remove & Replace Curb Ramp W Two New Directional Ramps or Equivalent.	/ith N/A	Ramp Length (in)	47.0	Yes	Ramp Slope (%)	6.0	
			Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	5.0	
			N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A	
The second se			N/A	Flare Slope LT (%)	3.2		Flare Slope RT (%)	4.0	
			N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	Yes	
ENDHAVEN_LIN			No	Landing Length (in)	N/A	Yes	DWS Provided?	Yes	
C C C C C C C C C C C C C C C C C C C		Surveyor Notes:	No	Landing Width (in)	N/A	Yes	DWS Contrast?	Yes	
		N/A	No	Landing Slope (%)	N/A	Yes	DWS Length (in)	24.0	
			No	Landing X Slope (%)	N/A	Yes	DWS Full Width?	Yes	
			N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	3.0	
			N/A	Shared Landing?	N/A				
		PROW/ADA:	Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	2.6	
		Not Found, R304.5.3, R304.2.1,	Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.9	
		R304.2.2-Perp, R304.3.2-Para,	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
		R305.2		X Walk 1 Direction	To E		X Walk 2 Direction	To N	
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	MEGWOOD DR	-		X Walk 1 Slope (%)	0.6		X Walk 2 Slope (%)	1.7	
Stop Condition-Street 2	StopSign			X Walk 1 X Slope (%)	2.1		X Walk 2 X Slope (%)	1.9	
Street 2 Name	ENDHAVEN LN		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	None			Road Slope (%)	2.2	N/A	Clear Space?	Yes	
				Road X Slope (%)	0.0	N/A	Clear Space to XWalk (in)	N/A	
			Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No	
		Total Cost: \$ 32	200.00	Obstruction Type			Storm Grate/Utility Type		
					N/A			N/A	
1									

s Surface Condition? (G/P)

Good

