

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 23181 Main Street: GLENEAGLES RD Cross Street: BAR HARBOR LN Location: NW **Overall Compliance: No Severity Score:** ADA ID: 6F29946F86FF Ramp Type: ParaDiag Initial Pass/Fail: Fail 12.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name Stop Condition-Street 1 Street 2 Name Stop Condition-Street 2 Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

R304.3.2

GLENEAGLES RD None **BAR HARBOR LN** StopSign

N/A N/A N/A N/A N/A N/A N/A Total Cost: 3200.00

Compliance Description Data Compliance Description Data N/A N/A N/A Ramp Length LT (in) Ramp Length RT (in) 63.0 N/A N/A Ramp Width LT (in) Yes Ramp Width RT (in) 60.0 N/A Ramp Slope LT (%) N/A No Ramp Slope RT (%) 11.6 N/A Ramp XSlope LT (%) N/A Yes Ramp XSlope RT (%) 1.9 N/A Landing Length (in) N/A N/A DWS Provided? N/A N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A Landing Slope (%) N/A N/A DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A Shared Landing? N/A N/A N/A Gutter Ponding? Gutter Slope (%) N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A Painted X Walk1? No N/A Painted X Walk2? No X Walk 1 Direction To S X Walk 2 Direction To E X Walk 1 Width (in) N/A N/A X Walk 2 Width (in) N/A X Walk 1 Slope (%) 1.6 X Walk 2 Slope (%) 4.8 X Walk 1 X Slope (%) 3.4 X Walk 2 X Slope (%) 0.2 Ramp inside XWalk1? N/A N/A Ramp inside XWalk2? N/A 1.1 N/A N/A Road Slope (%) Clear Space? Road X Slope (%) 6.3 N/A Clear Space to XWalk (in) N/A N/A Any Obstructions? N/A Storm Grate/Utility Hazard? N/A Obstruction Type Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good N/A Curb Slope (%) 6.9





