cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10026312 Main Street: FAIRVIEW_RD C					N/A	Location:	SE		
ADA ID: 6F650F7C86C6				nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	21.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
No. of Concession, Name	A A A A A A A A A A A A A A A A A A A	Possible Solutions:						liance Description	Data
		Remove & Replace Curb Ramp Two New Directional Ramps or	With	N/A	Ramp Length (in)	72.0	Yes	Ramp Slope (%)	5.9
			-	No	Ramp Width (in)	43.0	No	Ramp XSlope (%)	6.5
the second s	1. 化油油加加速度的C和空间	Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
FAIRVIEW	RD			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
e de la companya de la		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
The second se				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	统大、 武、"新行"			N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
The second second	R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
- Participation	13 . N	,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	2003 M				X Walk 1 Direction	To NE		X Walk 2 Direction	To W
The second	A STALL PROPERTY			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	FAIRVIEW RD	_			X Walk 1 Slope (%)	2.7		X Walk 2 Slope (%)	5.9
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	5.2		X Walk 2 X Slope (%)	1.5
Street 2 Name	ENTRANCE			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	3.1	N/A	Clear Space?	N/A
					Road X Slope (%)	2.7	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
1							1		

Yes Surface Condition? (G/P)

Good



