Access Compliance Report
Public Rights-of-Way
(Curb Ramps)

Intersection ID: 31447	**Main Street: RIDING_HILL_AV**	**Cross Street: GLENLUCE_AV**	**Location:**	**NW**
ADA ID: 6F8C3A58043F	**Ramp Type: NoRamp**	**Initial Pass/Fail: NoRamp Overall Compliance: No**	**Severity Score:**	**100**

Codes/Mitigation Info/Possible Solution



Possible Solutions:

Provide Curb Ramp Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

N/A

Total Cost: **$ 1500.00**

Field Measurements/Component Compliance

Compliance	Description	Data